

TOPSECRET 150600Z CITE 7324 25X1A

1MMEDIATE INFO 25X1A 25X1A

25X1A 25X1A

25X1A

25X1A

- 1. AIRCRAFT BEING CHECKED NOW TO DETERMINE ACTUAL HF OR BW PROBLEM. ANTICIPATE NOT MORE THAN 6 HOURS TO REPAIR OR REPLACE ENTIRE SYSTEM.
- 3. STANDING BY FOR INSTRUCTIONS.
- TOPSECRET TOR 0614Z 15 MAY 66

